

DATE: Sept 9, 1980

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

T225 R8W

C¹/₄ S29

Previous Renewal #'s none (originally set by BLM Survey)

Monument(s) Found: (Condition and Source) A 2 1/2" x 28" iron pipe

with a brass cap attached. Monument is pulled out of soil and lying on surface, because of recent land clearing in the surrounding area, no evidence of the monuments original position remains.

Cap is marked as follows:

U.S. DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

C¹/₄ S29

1965

^{of}
(Recondate stamped on cap is 1964)

Accessories Found: (Condition and Source) An original 6" fir, now

a 17" diam by 8" tall fir stump which is opened to find part of the remaining scribing which reads "S2"

From the preceding stump we measure N 6 1/2° W, 199³ ft. (302 lks) as per record to approximate the original location of the monument. From this position we find an original 19" now a 29" ^{DBH} White fir

#146X GLEN 6/1/1-21 Page 1 of 1 C

bearing $S86^{\circ}W$, 218^{\pm} ft.; this tree is partially opened to find the scribing "C'1/4". The most acceptable corner position is found to be at the intersection of the original distances. ^(302 lks.)
 from this position the 17" diam by 8" tall fir stump now bears $S05\frac{1}{2}^{\circ}E$, 199^{\pm} ft and the 29" white fir bears $N86\frac{1}{2}^{\circ}W$ $221\frac{1}{2}$ ft. distant. ^(336 lks.)
RENEWAL

Monument Set: (Procedure and Description) Upon measuring to point of the original intersecting distances and finding reasonable bearings to the original BT's this position is referenced out and the monument is replaced in the ground at this determined original location. The monument now protrudes 2" from the ground and is set firmly. We add
 RESET
 L.S. 1980 to stamping on brass cap.

New Accessories: (Description) A 25" DBH white fir bears
 $N84^{\circ}E$, 118^{\pm} ft. distant; tree is scribed "C'1/4 S29 CS BT" on a double blaze and is located in a random east-west fence line. An 8" D. fir bears $N64^{\circ}W$, 215^{\pm} ft distant; tree scribed "C'1/4 S29 CS BT" on a double blaze. All trees are retagged or tagged with DCSO BT tags.

Location and Comments: 19°E Compass Declination
 Monument is 53 feet DEED Agency
 south of a random Deputy State John Flinn Party Chief
 east-west fence line. Alfred [unclear] Sitekeeper
KAREN MOSELY Witnesses
BILL STEWART
