

T 26 S R 3 W
SPECIAL MEANDER CORNER
(SMC)

C
S | 9
C

DATE: APRIL 1, 1981

Condition Report Only
Not Found
 Renewed
Unrecorded
Surveyed In
Referenced Out

WITNESS CORNER SET

Previous Renewal #'s 128

Monument(s) Found: (Condition and Source) 1924 G.L.O. BRASS CAP

MONUMENT OUT OF GROUND, NEAR BEARING TREE DESCRIBED BELOW.

CAP IS STAMPED

" SMC "

591
1924

CAP IS ATTACHED TO A 1" X 3/8" IRON PIPE.

Accessories Found: (Condition and Source) NO ORIGINAL BEARING TREES FOUND

FROM RENEWAL #128 WE FIND A WHITE OAK 11 NOW 14 INCH DIAMETER WITH WELL HEALED DOUBLE BLAZE

BEARS S 65° E 22² FEET. (THIS IS THE ONLY BEARING TREE FOUND) WE SET A TEMPORARY

MARKER AT CORNER POSITION (IN LOG EXTENDING OUT OVER THE WATER) AND FIND A 16" ASH

BEARING SOUTH 18⁸ FEET (REC. SOUTH 15⁸ FEET) WITH BLM BOUNDARY TAG ATTACHED.


WE ARE NOT ABLE TO LOCATE ANY EVIDENCE OF BLAZE, SCRIBING, OR AXE WORK, ALONG

WITH NOTED DIFFERENCE OF RECORD DISTANCE, WE DETERMINE THAT THIS IS NOT A BEARING TREE.

229 ✓

U.S. File No. 61/19-22 Page of 2

N. UMPQUA RIVER



SPECIAL MEANDER COR POSITION

132 FT. MEAS.

40.0 FT. MEAS.

209 FT.
COMP. L
OCCUPIED

TEMP. INST. SET @ RANDOM

180°

WC SMC
TO SET

S 0° 56' W 137.94 FT. REC.

NO SCALE

4-1-81

L. E. MONBEAN

T. R. FLOUFF

SKETCH TO SHOW
PLACEMENT WC SMC

S 19 T 26 S R 3 W

T 26 S R 3 W AP# 7

FD BC

C & File No. 6/1/19-22