

TZ95 RIW
S29
C-E-E-E
V256
RLS 934
1971

DATE: APRIL 29, 1981

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) _____

2" IP. SET BY VICTOR MC LIND, DLS #934, IN
1971, FIRMLY SET, PROJECTING 4" ABOVE
GROUND, WITH B.C. MARKED AS ABOVE.

Accessories Found: (Condition and Source) _____

BTS MARKED BY MC LIND IN 1971:
A 22" O. FIR STUMP, S89³/₄° E, 18⁵ FT, WITH
S.M. "1/256 S29 BT" VISIBLE ON
PARTLY HEALED DOUBLE BLAZE.
A 12" O. FIR STUMP, S60° W, 50⁹ FT., WITH
NO MARKS VISIBLE.

X

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

I MARK NEW BTS:

A 14" D. FIR, S17°W, 54² FT, SCRIBED "1/256 S29
CSBT" ON DOUBLE BLAZE.

A 7" D. FIR, S88¹/₂°W, 37⁶ FT, SCRIBED "1/256
S29 CSBT" ON DOUBLE BLAZE.

Location and Comments:

19°E

USFS
LEONARD HERZSTEIN

TOM WOLFORD

JIM LANDRUM

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK *JHL*