

TZ9S RIW
C-N-SE-NE
1/256
S29
RLS 934
1971

DATE: MAY 4, 1981

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) _____

2" I.P. SET BY VICTOR MCLIND, OLS 934, IN 1971,
FIRMLY SET, PROJECTING 4" ABOVE GROUND, WITH
B.C. MARKED AS ABOVE.

Accessories Found: (Condition and Source) _____

BTS MARKED BY MCLIND IN 1971:

A 13" ICEDAR, N22³/₄°E, 19⁷ FT, WITH HEALED
DOUBLE BLAZE.

A 24" D. FIR STUMP, S63¹/₄°W, 19³ FT, WITH S.M.
"1/256 S29 BT" VISIBLE ON PARTLY HEALED DOUBLE
BLAZE.

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

F MARK NEW BT.:

A 7" D. FIR, 355 $\frac{1}{2}$ °W, 26 $\frac{1}{4}$ FT, SCRIBED "1256529CS BT"
ON DOUBLE BLAZE.

Location and Comments: 20°E Compass Declination

USFS Agency

LEONARD HERZSTEIN Party Chief
Notekeeper

JIM LANDRUM Witnesses

TOM WOLFORD