

T315 RIW
C 1/4, S30
1972
PE 2128

DATE: JUNE 18, 1981

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s M42-74

Monument(s) Found: (Condition and Source) _____

2" I.P. WITH BRASS CAP MARKED AS ABOVE,
SET BY WILLIAM BARNES IN 1972, FIRMLY
SET, PROJECTING 6" ABOVE 2' DIAMETER
MOUND OF STONE.

Accessories Found: (Condition and Source) _____

BTS MARKED BY BARNES IN 1972:
14" D. FIR STUMP, S10°W, 63 1/2 FT., WITH SCRIBE
MARKS VISIBLE ON PARTLY HEALED DOUBLE BLAZE.

14" D. FIR, N49 1/2°W, 22 1/2 FT., WITH SCRIBE
MARKS VISIBLE ON PARTLY HEALED DOUBLE BLAZE.

#197 ✓

U.S. FILE NO. 61/27-5 Page of
C

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

I MARKED NEW BT. :

11" W. FIR, N 24³/₄° E, 27³/₄ FT., SCRIBED

"C 1/4 530 CS BT" ON DOUBLE BLAZE.

Location and Comments:

19¹/₄°

Compass Declination

USFS

Agency

LEONARD HEARSTEN

Party Chief

JIM LANDRUM

Notekeeper

TOM WOLFORD

Witnesses

OK
[Signature]