


DATE: JULY 16, 1981



Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 29

Monument(s) Found: (Condition and Source) _____

1/4" IP, FIRMLY SET, PROJECTING 6" ABOVE
GROUND WITH BRASS CAP MARKED AS
ABOVE, SET BY JAMES BYRON, DEPUTY
DOUGLAS CO. SURVEYOR IN 1957.

Accessories Found: (Condition and Source) ORIGINAL BTS:

A 18" D. FIR, S36°W, 20.5 FT, WITH FRAGMENTARY
SCRIBE MARKS VISIBLE ON PREVIOUSLY
OPENED BLAZE.

A 48" D. FIR, S80°E, 5.3 FT, ~~BT~~ AND
RESCRIBED BY BYRON IN 1957 WITH
SCRIBE MARKS "1/4 S5C5BT" VISIBLE ON

Page 61/27-23 of _____
C. S. File No. 61/27-23

BARK BLAZE

AND BT MARKED BY BYRON IN 1957:

A 12" S. PINE, N23°W, 22[±] FT, WITH HEALED
DOUBLE BLAZE.

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments:

U.S.F.S.

LEONARD HERZSTEIN

JIM LANDRUM

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

