

T 29 S R 9 W

DATE: AUGUST 11, 1981

1/4 S 27 | S 26

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 11, 63, 76

Monument(s) Found: (Condition and Source) ORIGINAL QUARTER SECTION

POST NOT FOUND. A 3/4" (ID) X 30" (REC. 1" X 30") IRON

PIPE FOUND FROM RENEWAL # 11.

Accessories Found: (Condition and Source) ORIGINAL BT'S.

1) FOUND A 31" DIA CEDAR STUMP (REC. 30") BEARS S 60° E

19 1/2 FEET. NO BLAZE OR SCRIBING FOUND.

REN. # 11 BT. 2) A 10" CEDAR NOW A DEAD WINDFALL BEARS

N 62° E 14 5/8 FT. FOUND SCRIBING "BT", RENEWAL # 63 BT

3) A W. FIR 8 NOW 20 INCH, BLAZE WELL HEALED, BEARS S 55° E 48 3/4 FT.

RENEWAL # 76 BT 4) A W FIR 9 NOW 22 INCH, BLAZE WELL HEALED,

93

BEARS S 6 1/2° W 68° FT.

RENEWAL

Monument Set: (Procedure and Description) A 1" x 30" IRON PIPE

WITH ATTACHED BRASS CAP STAMPED DOUGLAS COUNTY SURVEYOR

T 29 S R 9 W

1/4 S 27 | S 26

1981

SET ED 3/4" IRON PIPE ALONGSIDE

New Accessories: (Description) _____

A 10" DIA. W. FIR BLAZED AND SCRIBED "1/4 S 27 CS BT" BEARS N 39 1/2° W 62 1/2 FEET.

A 14" DIA. W. FIR BLAZED AND SCRIBED "1/4 S 26 CS BT" BEARS N 75° E 49 3/4 FEET.

Location and Comments:

19° EAST

Compass Declination

MONUMENT IS 3 1/2 FEET

DOUGLAS CO. SURVEYOR

Agency

EAST OF A N-S FENCE.

LARRY E. MOWREAN

Party Chief

Larry E. Mowrean DEPUTY

Notekeeper

D.L. STEWART

Witnesses

OK [Signature]