

T245

DATE: 8-12-81

S19	S20
S30	S29

RIW

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s # 66

Monument(s) Found: (Condition and Source) FD. DCSO BRASS

CAP PER REN. #66 PROTRUDING 14" OUT OF THE GROUND. THE CAP IS MARKED:

COUNTY SURVEYORS OFFICE
 T245 RIW

S19	S20
S30	S29

 1966

FD. Orig. COR STONE 12"x8"x8" MARKED WITH 2 NOTCHES ON SOUTH FACE & 5 NOTCHES ON EAST FACE LEANING AGAINST THE NE SIDE OF BRASS CAP.

Accessories Found: (Condition and Source)

✓ FD. orig. 20" now 24" FIR STUMP, WHICH HAS BEEN TREATED AND HAD THE BARK REMOVED (FACE NO LONGER RECOGNIZABLE), BEARS N 73° E 25° (REC. 25¹)

✓ FD. orig. 16" now 18" FIR STUMP WHICH HAS BEEN TREATED AND HAD THE BARK REMOVED (FACE NO LONGER

RECOGNIZABLE), BEARS $S41^{\circ}E 24^{\circ}$ (REC. $S45^{\circ}E 25^{\circ}$)

✓ ORIG. 8" FIR HAS BEEN CUT AND STUMP DISLODGED BY LOGGING. ✓ ORIG. 20" CEDAR HAS BEEN BLADED OUT DURING LOGGING. ✓ 8" HEMLOCK PER REN #66 HAS BEEN BLADED OUT DURING LOGGING.

~~REDACTED~~

~~REDACTED~~: (~~REDACTED~~)

FD UNRECORDED 29" FIR STUMP, TREATED, BARK GONE, AND SCRIBED "T295 RIW S30 BT" BEARS $S73^{\circ}W 33^{\circ}$.

FD UNRECORDED 36" FIR STUMP, TREATED, BARK GONE, AND SCRIBED "T295 RIW S19 BT" BEARS $N33^{\circ}W 52^{\circ}$. BOTH UNRECORDED BT'S HAVE 1981 BLM BT TAGS.

New Accessories: (Description) SET BOAT SPIKE STAMPED "BO 1" IN TOP OF ORIG. 20" FIR NOW 29" STUMP, BEARS $N73^{\circ}E 25^{\circ}$.

SET BOAT SPIKE STAMPED "BO 2" IN TOP OF ORIG 16" FIR NOW 18" STUMP, BEARS $S41^{\circ}E 24^{\circ}$. SET BOAT SPIKE STAMPED

"BO 3" IN TOP OF 29" FIR STUMP, BEARS $S73^{\circ}W 33^{\circ}$.

SET BOAT SPIKE STAMPED "BO 4" IN TOP OF 36" FIR STUMP, BEARS $N33^{\circ}W 52^{\circ}$. ALL STUMPS HAVE DCSO BT TAGS

Location and Comments:	<u>19° E</u>	Compass Declination
	<u>DCSO</u>	Agency
	<u>Gregory E. Zuehl</u>	Party Chief
	<u>Greg Zuehl</u>	Notekeeper
	<u>DEBBIE STEWART</u>	Witnesses

OK
[Signature]