

T 22 S R 6 W

1/4 52 | S 1

DATE: 8-27-81

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) NONE

Accessories Found: (Condition and Source) 1. ORIGINAL 8" DIA FILE

NOW A 30" DIA. STUMP DECAYED. WE OPEN STUMP AND FIND

GOOD SCRIBING "BT". OTHER ORIGINAL BT NOT FOUND.

#137 4

U.S. File No. 61/27-34

Page of C

RENEWAL

Monument Set: (Procedure and Description) AT RECORD BEARING AND

DISTANCE OF FOUND ORIGINAL BEARING TREE (TREE BEARING S 58° W 47^S FEET),

WE SET A 1" X 30" IRON PIPE WITH BRASS CAP ATTACHED 22" INTO THE

" DOUGLAS COUNTY SURVEYOR "

GROUND. CAP IS STAMPED

22 S R 6 W
1/4 S 21/31
1981

New Accessories: (Description)

1) A W. OAK 16" DIA. BLAZED AND SCRIBED "1/4 S 1 C S B T" BEARS S 17° E 7^S FEET.

2) A W. OAK 13" DIA. BLAZED AND SCRIBED "1/4 S 1 C S B T" BEARS S 72 1/2° E 47^S FEET.

3) A W. OAK 11" DIA. BLAZED AND SCRIBED "1/4 S 1 C S B T" BEARS N 52 1/2° E 17^S FEET.

4) A W. OAK 12" DIA. BLAZED AND SCRIBED "1/4 S 2 C S B T" BEARS N 0 1/2° W 34^S FEET.

Location and Comments:

FENCE CORNER S 48 1/2° W
30° FT. FNC RUNNING
N-S-E

19° EAST

Compass Declination

DOUGLAS Co. SURVEYOR

Agency

LARRY E. MONREAN DEP.

Party Chief

Farry E. Monrean

Notekeeper

T. R. PLOUFF

Witnesses

ROBERT G. DEAN

DON CHURCHILL

OK *[Signature]*

137 ✓