

T 26 S R 2 W

DATE: 9-17-81

30 | 29
31 | 32

Condition Report Only
Not Found
 Renewed
Unrecorded
Surveyed In
Referenced Out

Previous Renewal #'s NONE ON RECORD

Monument(s) Found: (Condition and Source) FD 2 1/2" ALUM.

CAP ON 3/4" IP (NOT OF RECORD) FIRMLY SET

PROTRUDING 6" OUT OF A SMALL MOUND OF

STONE MARKED:

U.S. P.C. PROPERTY COR.

T 26 S R 2 W

30 | 29
31 | 32

PE 4287

DO NOT DISTURB

FD NO TRACE OF

ORIG. STONE

FROM WHICH:

Accessories Found: (Condition and Source)

FD ORIG. 10" NOW 15" FIR BLOWDOWN WITH WELL HEALED
BLAZE BEARS N 66° E 16² FT. TO STUMP HOLE.

FD ORIG. 12" NOW 14" FIR BLOWDOWN WITH WELL HEALED
BLAZE BEARS S 7° E 11² FT TO STUMP HOLE.

FD. ORIG. 20" NOW 23" CEDAR, ALIVE, WITH WELL HEALED
BLAZE BEARS S 38° W 13² FT.

#122 ✓

FD ORIG. 14" NOW 23" FIR WITH WELL HEALED
BLAZE BEARS N7°W 19² FT (REC. N9°W 18⁵ FT)

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

10" CEDAR BEARS N75°E 40¹ FT SCRIBED

"T 265 R2W S29 CS BT" IN DOUBLE BLAZE

9" CEDAR BEARS S3°E 12² FT SCRIBED

"T 265 R2W S32 CS BT IN DOUBLE BLAZE

Location and Comments:

COR IS NORTH
40 FT. OF
ROAD &

19°E
DCSO
Gregory E. Reibel
GREG QUDEK
DEBBIE STEWART

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
[Signature]