

T 22 S R

DATE: 9-21-81

S30	L
S31	W

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s 63

Monument(s) Found: (Condition and Source) A 1" DIA IRON PIPE WITH

ATTACHED BRASS CAP STAMPED  
COUNTY SURVEYOR'S OFFICE

T 22 S

R	S30	R
L		6
W	S31	W
	1960	

MONUMENT IS FIRMLY SET, PROTRUDING 8 INCHES ABOVE GROUND.

Accessories Found: (Condition and Source) 1) ORIGINAL 36" DIA

CEDAR DESCRIBED "BY BYRON (REN #63) "T 22 S E 6 W S 30 81"

LEGIBLE. THIS TREE NOW A BADLY DECAYED STUMP WITH DEBRIS

PILED AGAINST IT. STUMP BEARS N 83° E 155<sup>2</sup> FEET TO

APPROXIMATE CENTER (REC. N 83° E 156<sup>4</sup> FEET)

2) THE ORIGINAL 48" DIA FIR NOW A DECAYED STUMP WITH

NO SCRAWL OR BLAZE REMAINING BEARS S 29° E 96<sup>L</sup> FEET TO

#140 T 22-7 ✓  
 #140 T 22-6 ✓

APPROX. CTR. (BEC. S 30° E 93<sup>1</sup>/<sub>2</sub> FEET).

3) FROM RENEWAL NO. 63 A 55" CEDAR NOW A SNAG SCRIBED

"TZZS R6W CS BT" VISIBLE BEARS S 76° E 128<sup>0</sup> FEET.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description)

1) A.D. FIR 12" DIA SCRIBED "TZZSR6W S30CS BT" ON DOUBLE BLAZE BEARS S 28<sup>0</sup> E 42<sup>0</sup> FEET.

2) A.D. FIR 14" DIA SCRIBED "TZZSR6W S30CS BT" ON DOUBLE BLAZE BEARS N 88<sup>1</sup>/<sub>2</sub>° E 46.5 FEET.

3) A.D. FIR 16" DIA SCRIBED "TZZSR6W S30CS BT" ON DOUBLE BLAZE BEARS N 71° E 42<sup>0</sup> FEET.

Location and Comments:

4 INCHES "T" IRON  
BEARS S 8<sup>1</sup>/<sub>2</sub>° E 6<sup>25</sup> FT.

19° EAST

Douglas Co. Surv. Off.

LARRY E. MONREAN

Jean C. Monrean DEPUTY

T.E. FLOWFF

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

*OK*