

T 26 S R 1 W

S 7 | S 8
S 18 | S 17

DATE: 9-29-81

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 28 & BLM RESURVEY

Monument(s) Found: (Condition and Source) ORIGINAL CORNER MONUMENT

AND BRASS CAP SET BY BYRON (REN. # 28) NOT FOUND.

Accessories Found: (Condition and Source) ORIGINAL 20 INCH DIA. FIR NOW

A 42 INCH DIA STUMP BEARS N 85° E 15 1/2 FEET, THIS TREE CUT LOW - NO

SCRIBING REMAINS, 2) ORIGINAL 18 NOW 32 INCH DIA. FIR BEARS
BARK SCRIBING "TRW" REMAINS

N 82 1/2° W 38 1/2 FEET (ORIG. REC. N 85° W 40 1/2 FEET) 3) STUMP HOLE

AT RECORD BEARING AND DISTANCE TO SE ORIGINAL BT REMAINS.

FACE MEASUREMENT TO ORIGINAL DIAMETER USED FOR DISTANCES TO

ORIGINAL BEARING TREES,

110 ✓

TREES FROM RENEWAL # 28 1) A 5" HEMLOCK NOW AN UPROOTED 8" DIA
 STUMP BEARS S 74 1/2° E 36 3/4 FEET (REC. S 77° E 39 1/2 FEET) 5) A 6" NOW 10" DIA. W. FIR
 WITH WELL HEALED DOUBLE BLAZE BEARS N 67° W 29 3/4 FEET (REC. N 68° W) 6)
 A P. FIR 8 NOW 12 INCH DIA WITH WELL HEALED DOUBLE BLAZE BEARS S 84° W
 36 3/4 FEET.

RENEWAL

Monument Set: (Procedure and Description) AT POSITION FROM WHICH
 BEARINGS AND DISTANCES ARE NOTED ABOVE SET A 1" X 30" IRON PIPE
 WITH ATTACHED BRASS CAP, CAP IS STAMPED
 "DOUGLAS COUNTY SURVEYOR
 T 26 S R 7 W
 57/58
 518 517
 1981

MONUMENT LIES ON STEEP NTHLY SLOPE MAUND STONE
 AROUND NTHLY BASE, CAP PROTRUDES 2 INCHES ABOVE GROUND.

New Accessories: (Description)

A 1 1/4" DIA HEMLOCK DOUBLE BLAZED AND SCRIBED "T 26 S R 7 W S 17 CS. 81" BEARS
 S 81° E 63 1/4 FEET TO CENTER.

Location and Comments:	19° EAST	Compass Declination
	DOUGLAS CO. SURV. OFF.	Agency
	LARRY E. MOIREAN (D.P.)	Party Chief
	<i>Jerry E. Moore</i>	Notekeeper
	T. R. FLOUFF	Witnesses

OK *JEF*