

T30S R2W

DATE: 9-30-81

1/4

S28

X

S33

Condition Report Only

Not Found

✓ Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s #25, #74, #86, #220

Monument(s) Found: (Condition and Source) FD. 2" x 30" I.P.

per ren #220

WITH BRASS CAP, LYING ON GROUND

NEAR ITS CORRECT LOCATION. THE CAP

WAS KNOCKED OUT BY A CAT DURING

A RECENT FOREST FIRE. I THEN

ESTABLISHED A TEMP. POSITION BASED

ON THE FOLLOWING PER REN. #220

CAP MARKED: "T30S R2W"

1/4

S28

S30

LS 866  
1979

Accessories Found: (Condition and Source) FD. 24" FIR STUMP,

BURNED FACE, BEARS S 76° W 101<sup>2</sup> FT. FD. 18" FIR

STUMP, BURNED, "S33 BT" VISIBLE, BEARS S 79° W 108<sup>5</sup> FT.

FD. 24" MADRONE BEARS N 45° E 157<sup>3</sup> (REC 156<sup>6</sup>)

REN. 220

WITH SCRIBED "T30S R" VISIBLE IN BARK.

FD. 24" NOW 25" CEDAR BEARS S 57° E 153<sup>9</sup>

WITH "T30S R2W S33 1/4 S BT VISIBLE IN UNHEALED

BLAZE

#235  
#135 ✓

RENEWAL

Monument Set: (Procedure and Description) I REF. MY  
TEMP POSITION, THEN RESET FD.  
BRASS CAP AT THAT LOCATION. CAP NOW  
IS IN A STEEP FIRETRAIL PROTRUDING  
4" OUT OF GROUND. I ADD MARKS:

~~Notes:~~ (Description) "RESET"  
1981

Location and Comments: 19°E Compass Declination  
DCSO Agency  
Gregory C. Zulew Party Chief  
Greg Quibell Notekeeper  
TERRIE PLOUFF Witnesses  
TERESA BULKY

OK  
JRM