

T 29 S R 7 W

DATE: 10-6-81

S 23	
S 26 1/2	S 26

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s 1924 RESURVEY, REN. # 28

Monument(s) Found: (Condition and Source) AN UNRECORDED IRON PIPE

WITH ALUMINIUM CAP, BUREAU OF LAND MANAGEMENT, MONUMENT FIRMLY

"T 29 S R 7 W"

IN PLACE. CAP IS STAMPED

S 23	
S 26 1/2	S 26
1981	

ALONG SOUTHEAST EDGE OF BLM MONUMENT IS A STONE BURIED

NEARLY FLUSH WITH GROUND. THE STONE MEASURES 6 1/2 X 7

INCHES ACROSS THE TOP. THE TOP OF THE STONE IS MARKED

" 2 26 1/2 ", THE EAST FACE HAS TWO NOTCHES.

NOTE: BEARINGS AND DISTANCES RECORDED ARE TAKEN

FROM BLM CAP POSITION.

Accessories Found: (Condition and Source) NO ORIGINAL OR 1924

RESURVEY BEARING TREES WERE FOUND.

TREES PER RENEWAL # 28

1) A CEDAR 8" DIA. WITH WELL HEALED DOUBLE BLAZE BEARS S 18° W

16 1/2 FEET (REC. S 15° W 16 FEET).

2) A FIR 8" NOW 14" DIA. WITH WELL HEALED DOUBLE BLAZE

BEARS S 17 1/2° W 14 FEET (REC. S 20° E)

#268 ✓

G. E. H. No. 61/29-4

Page of

C

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) _____

1) A FIR 12" DIA. SCRIBED "T29S R7W S26 CS BT" ON A
DOUBLE BLAZE BEARS S 54° E 11² FEET.

2) A FIR 8" DIA SCRIBED "S23CS BT" ON A DOUBLE
BLAZE BEARS N 44½° W 8⁶ FEET.

Location and Comments: 19° EAST Compass Declination
DOUG. CO. SURV. OFF. Agency
LARRY E. MONREAN Party Chief
Jerry A. Munn DEPUTY Notekeeper
J.P.H. BULEY Witnesses