



DATE: 3/02/82

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 158

Monument(s) Found: (Condition and Source) 2 1/2" BRASS CAP

ON 1" IRON PIPE. FURN, PROJECTING 14"

SET BY DOUGLAS CO. SURVEYORS OFFICE IN
1968

Accessories Found: (Condition and Source)

ORIG. BT - 24" P.O.N. PINE - BEARS S 81° W, 285⁸ FT; NOW SNAG

SCRIBES VIS "T30S R2W S34" ON PREV. OPENED DBL. BLAZE

22" P. PINE - BEARS N 5° W 94¹ FT, PART. HEALED BLAZE

W/FRAG SCRIBE MARKS VIS (By Co. Surveyor, 1968) Ren # 158

14" D.FIR, BEARS N 2° E, 103² FT, HEALED FACE - NOW SNAG

(By Co. Surveyor, 1968)

16" D.FIR, BEARS S 81° E, 74⁴ FT, HEALED FACE (Co. Surveyor 1968)

~~#158~~ 245 X

G. L. E. No. 61/32-8 Page 1 of 1

10" D. FIR, BEARS N 89° E 132 ⁵/₈ FT. PART. HEADED

DBL. BLAZE - Scribes Vis "T30S RZW S 26" BT,

BRASS WASHER W/STAMP "536" NAILED TO LOWER

FACE. BT TAG MARKED BY BAUGHMAN 2/78.

(1ST NOT OF RECORD) THIS BT SCARRED BY
RECENT ROAD BUILDING
RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) NEW BT: 20" P. PINE

BEARS S 88° W, 108 ⁶/₈ FT. SCRIBED "T30S RZWS 34CS"
"BT" ON DBL. BLAZE

PAINTED 1" RED BAND & PAINTED BLAZES ON ALL BT'S
& ADDED 54-4 ATTENTION SIGNS TO BT'S

Location and Comments:

CORNER NOW
~~B~~ LOCATED 2150'
SOUTH OF NEW
ROAD

18 1/2° E
U.S.F.S.
JIM LANDRUM
LEONARD HERTZSTEIN

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
[Signature]