

GOVERNMENT CORNER RESTORATION FORM

Township 31S Range 7W Sec. 9 County DOUGLAS

State OR Date 2-14-83 No. _____

Corner Designation

T 31S R 7W

1/4 9 | 10

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #92; 1974 RESURVEY; 1979 RESURVEY

Monument(s) Found: (Condition and Source)

FD. ORIGINAL CORNER TREE, A 52" FIR WITH WELL HEALED BLAZE ON WEST SIDE AND "1/4 S9/S10" BARK SCRIBED ON SW SIDE.

FD 1 1/2" IP WITH BRASS CAP ATTACHED, FIRMLY SET, PARTIALLY UNDER WEST SIDE OF CORNER TREE.

MONUMENT DETAIL

SURVEYORS
OFFICE

COUNTY T 31S R 7W
1/4 S9 | S10

1971

Accessories Found: FROM CORNER TREE

FD. ORIG. 16" OAK NOW 18" WITH ROTTED HOLE IN THE AREA A BLAZE WOULD HAVE BEEN LOCATED, BEARS S 88° E 30 1/2 FT. (REC. S 78° E 34 1/2 FT.)

FD. ORIG. 24" FIR NOW 41" WITH SCRIBED "1/4 S" PER REA #92 VISIBLE IN PREVIOUSLY OPENED BLAZE, BEARS N 88° W 32 1/2 FT. (REC. N 85° W 36 1/2 FT.)

FD. 12" FIR PER REA #92, NOW 12" WITH WELL HEALED DOUBLE BLAZE, BEARS N 2° E 30 1/2 FT. (REC. 30 1/2)

FD. 2 1/2" IP WITH BRASS CAP ATTACHED, MARKED "T 31S R 7W S9 RM 1974 33 FT. (REC. SAYS S10) AND AN ARROW POINTING TO THE CORNER, BEARS N 75° W 29 1/2 FT. (REC. N 75 E 33 FT.)

FD. 2 1/2" IP WITH BRASS CAP ATTACHED, MARKED "T 31S R 7W S9 RM 1974 33 FT." AND AN ARROW POINTING TO THE CORNER, BEARS S 75° W 29 1/2 FT. (REC. 33 1/2 FT.)

#113 X

CLERK 62/7-13C

