

GOVERNMENT CORNER RESTORATION FORM

Township 24S Range 1 W Sec. 21 County DOUGLAS

State OREGON Date 9-27-83 No. _____

Corner Designation

$\frac{1}{4}$ $\frac{S 21}{S 28}$

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals # 51

Monument(s) Found: (Condition and Source)

FROM ORIGINAL SURVEY POSSIBLE CORNER
STONE NOTED PER RENEWAL # 51, OUT
OF GROUND. ALSO FOUND IRON PIPE AND
BRASS CAP PER RENEWAL # 51 FIRMLY
SET, MARKED AS NOTED.

COUNTY SURVEYORS OFFICE

T 24S

$\frac{1}{4}$ $\frac{S 21$

$\frac{S 28$

R 1 W

1966

Accessories Found:

ORIGINAL

1. A FIR 42 NOW 52 INCH DIA. WITH WELL HEALED BLAZE BEARS N 13° E 21 2 FEET (REC. 22 4)
2. A 36" FIR NOW A STUMP WITH PARTIALLY OPENED BLAZE AND VISIBLE SCRIBING BEARS S 43° W 16 5 FEET (REC. S 46° W 17 3 FEET).

FROM RENEWAL # 51

3. A 7" D. FIR WITH SCRIBING VISIBLE IN A PARTIALLY HEALED BLAZE BEARS N 18° E 7 2 FEET TO BLAZE (REC REC.) AND N 13 1/2° E 8 5 FEET TO ROOT CROWN.

6" FIR S 70° E IS DOWN

#142 X

C. S. Ellis

62/9-4 C

