

T 27S R6W

DATE: 10-1-81

SEC. 1

SW DLC  
#62

NW DLC  
#39

OK  
CORNER  
CONSTRUCTION  
DID NOT  
DISTURB

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s #65

Monument(s) Found: (Condition and Source) FD. 3/4" IR

WITH IRON COLLAR AROUND IT  
IN THE CENTER OF HOOKER RD.

3/4" IR PER REV. #65

Accessories Found: (Condition and Source) \_\_\_\_\_

ALL ACCESSORIES APPEAR  
TO HAVE BEEN DESTROYED.

#161 X

CS ~~62/9-14~~ / 30  
C. S. File No. ~~62/9-14~~ Page of C  
62/9-14

RENEWAL

Monument Set: (Procedure and Description)

New Accessories: (Description)

<sup>78" x 30" GP</sup>  
SET ~~34"~~ IR N 89° W 31 <sup>73</sup> FT

<sup>56" x 30" GP</sup>  
SET ~~34"~~ IR S 89° E 29 <sup>09</sup> FT

SET TACK W/ RED FLAGGING IN

BRACE POLE S 89° E FOR SIGHT

Location and Comments:

19° E

Compass Declination

DCSO

Agency

Gregory E. Zittel

Party Chief

Greg Duben

Notekeeper

TERRIE PLUMER

Witnesses

TERESA BUEY

OK  
JEM