

GOVERNMENT CORNER RESTORATION FORM

Township 27 S Range 2 W Sec. 8 County DOUGLAS

State OREGON Date 2-14-84 No. _____

Corner Designation

1/4 SB/59

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals *2(1957) *III(1966) 1971 BLM SURVEY

Monument(s) Found: (Condition and Source)
FROM RENEWAL *2 A 1" DIAM. IRON PIPE WITH BRASS CAP AT FENCE CORNER.

DID NOT LOCATE ORIGINAL BASALT STONE.

MONUMENT DETAIL

COUNTY SURVEYORS OFFICE

T 27 S
1/4 SB/59
R 2 W
1957

Accessories Found:

1. ORIGINAL 18" NOW 30" DIAM. FIR STUMP 3 1/2 FEET HIGH WITH PARTIALLY HEALED BLAZE BEARS N 63° W 22 3/4 FT (AGREES WITH REN. NO. III - ORIG NOTES AND 1971 BLM NOTES CALL N 66° W 24 1/2 FT, 23 1/2 FT RESPECTIVELY)

ORIG. SW BT NOT FOUND

NEW BT 8" FIR N 21 E SCRIBED IN RENEWAL *2 NOT FOUND

2. REN. *III BT A CEDAR 11 NOW 14 INCH DIAM. WITH WELL HEALED DOUBLE BLAZE BEARS S 58° W 43 8/10 FEET.

✓
223

C.S. File No. 62/16-10 . C ✓

