

GOVERNMENT CORNER RESTORATION FORM

Township 20S Range 11W Sec. 1 County DOUGLAS

State OR Date 9/18/84 No. _____

Corner Designation

S1 | 56
S12

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals ^{T. 20-11} #100 ^{#47 T. 20-10}

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)
A 2 1/2" DISK ON A 2" I.P. FIRMLY
SET AND PROTRUDING 1.1 IN.
ABOVE GROUND. MARKED AS NOTED
(PER. REN#100)

T20S T20S

S1 |
S12
R 11W | 56

1971
4185

Accessories Found:

A 8" NOW A 24" DIA. MAPLE 2' HIGH STUMP. TREE LAYS IN
BOTTOM OF CREEK. SCRIB. VISIBLE ON A PREVIOUSLY OPENED
BLAZE "SR", STUMP BEARS N45°E, 19.8' (ORIG.)

A 18' NOW A 26" DIA. D. FIR WITH A OPENED PARTIALLY
REHEALED SINGLE BLAZE BEARS S3°W, 25.6' (REC. 23.93')
(PER REN#100)

A 24" NOW A 28" DIA. D. FIR WITH A WELL HEALED SINGLE BLAZE
BEARS N33°W, 76.4' (REC. N30°W, 75.29'). (PER REN#100)

