

GOVERNMENT CORNER RESTORATION FORM

Township 26S Range 2W Sec. 13 County DOUGLAS

State OREGON Date DEC. 20, 1984 No. \_\_\_\_\_

Corner Designation

$\frac{1}{4}$   $\frac{S13}{S24}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals # 26, 1916 RESURVEY

Monument(s) Found: (Condition and Source)

APPROXIMATELY 5x6x12 INCH STONE FROM 1916 RESURVEY, MARKED "41-"; STONE SET IN GROUND ON WEST EDGE OF BC. MONUMENT. FROM REN# 26 A BRASS CAP ON AN IRON PIPE MARKED AS AT RIGHT, FIRMLY SET AND PROTRUDING 12 INCHES FROM GROUND.

COUNTY SURVEYORS OFFICE

T26S R2W

$\frac{1}{4}$   $\frac{S13}{S24}$

1961

Accessories Found:

NO EVIDENCE OF ORIGINAL SW FIR FOUND. ORIGINAL CEDAR, 8 IN. DIAM. ALSO A 30 INCH DEAD AND FALLEN CEDAR WITH OPENED BLAZE, PARTIAL SCRIBING VISIBLE. ROOT HOLE OF THIS TREE BEARS N 55° E, 9.9 FT DIST (AS PER RECORD).

FROM 1916 RESURVEY NO EVIDENCE OF SW BEARING TREE FOUND. A PRIVATE ROAD HAS BEEN BUILT THROUGH THIS LOCATION.

FROM RENEWAL # 26 BOTH B.T.'S FOUND. AN 11" I. CEDAR NOW A 20 INCH DBH INCENSE CEDAR, WITH A WELL HEALED DOUBLE BLAZE NO SCRIBES. BEARS N 32 1/2° E, 38 3/4 FT. DIST. (AS PER RECORD). A 13" D. FIR NOW A 21 INCH D.B.H. DOUGLAS FIR WITH A WELL HEALED DOUBLE BLAZE NO SCRIBING VISIBLE, BEARS S 12° W, 50.7 FT. (AS PER RECORD).

#1334

C.S. File No. 62/21-10 C

