

GOVERNMENT CORNER RESTORATION FORM

Township 27S Range PW Sec. 7 County DOUGLAS

State OREGON Date 12/13/84 No. _____

Corner Designation

1/4 S12 | S7

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

#62-107 T27-3

Previous Renewals #8, #99, ^{T27-2} BLM 1979 RESURVEY

Monument(s) Found: (Condition and Source)

A DCSSO DISK ON A I.P. PROTRUDING
 8 IN. ABOVE A 2Y2 FT DIA. MOUND
 OF STONE, MARKED AS NOTED (PER.
 REN. #99).
 NO VISIBLE EVIDENCE FOUND OF 1/2"
 I.P. NOTED IN REN #8 AND #99.
 NO EVIDENCE FOUND OF 3/4" I.P.
 SET IN 1947 (PER CS #40/56).

CS #40/56

COUNTY SURVEYORS OFFICE

T27S

R 3 1/4 S12 | S7 2
 W W

1968

Accessories Found:

14" NOW A 28" DIA. 3 FT HIGH ROTTED AND BURNT STUMP
 NO SCRIBING FOUND. BEARS N 36°W, 7.8' TO CENTER,
 (REC. N 15°W, 5.3') ORIG. BT

10" NOW A 16" DIA. D. FIR WITH A WELL HEALED SINGLE BLAZE
 BEARS S 55 1/2°W, 25.7 FT WICH AGREES WITH 1979 BLM
 RESURVEY (REC S 57°W, 26.5' PER REN #8 + 99).
 (BT PER REN #8).

6" NOW A 14" DIA. D. FIR WITH A WELL HEALED SINGLE BLAZE
 BEARS S 13°E, 20.8 FT WICH AGREES WITH 1979 BLM RESURVEY
 (REC. S 15°E, 21.0' PER REN #8 + 99) (BT PER REN #8).

#139 T27-3 ✓
 #229 T27-2 ✓

C.S. File No. 62/21-24C

