

GOVERNMENT CORNER RESTORATION FORM

Township 27S Range 5W Sec. 23 County DOUGLAS

State OR Date 11/20/84 No. _____

Corner Designation

W. C. TO
1/4 S23 | S24

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #135 THAT INCLUDES RENEWALS IN 1969 AND 1978

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A DCSO DISK ON A I.P. PROTRUDING 7" ABOVE GROUND (PER. REN #135) MARKED AS NOTED

COUNTY SURVEYOR'S OFFICE

1/4 COR

T27S | R5W

23 | 24

W. C. 35' SOUTH TO 1969

Accessories Found:

NO BT'S TO 1/4 COR PRIOR TO W.C. BEING SET WERE FOUND.

20" NOW A 20" DIA. 3 1/2 FT HIGH ADDED STUMP, POSSIBLE BLAZE NO SCRIBING FOUND, BEARS N17°W, 29.9 FT (PER. REN. #135).

12" NOW A 14" DIA. B. OAK WITH A WELL HEALED SINGLE BLAZE BEARS S27°E, 16.9 FT. (PER REN #135).

8" NOW A 10" DIA. TRIPLE TRUNKED B. OAK, WITH A WELL HEALED DOUBLE BLAZE ON EAST TRUNK, BEARS S86°W, 31.3 FT (REC. S88°W) (PER. 1969 REN. #135).

#165+

