

GOVERNMENT CORNER RESTORATION FORM

Township 28S Range 8W Sec. 8 County DOUGLAS

State OR Date 8/9/84 No. _____

Corner Designation

$\frac{1}{4}$ $\frac{S8}{S17}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals BLM 1972 DEPENDENT RESURVEY

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A BLM DISK ON A I.P. PROTRUDING
6 IN. ABOVE GROUND MARKED AS
NOTED. (PER 1972 BLM RESURVEY)

T28S 8W

$\frac{1}{4}$ $\frac{S8}{S17}$

1972

Accessories Found:

A 17" NOW A 21" DIA. D. FIR 7 FT. HIGH STUMP WITH A SINGLE WELL
HEALED BLAZE BEARS N 13° E, 48.2 FT (PER 1972 BLM RESURVEY).

A 10" DIA. D. FIR WITH A SINGLE WELL HEALED BLAZE
BEARS S 17° W, 9.7 FT (REC S 14° W IS TO CENTER OF TRUNK).
(PER 1972 BLM RESURVEY).

#181 X

