

GOVERNMENT CORNER RESTORATION FORM

Township 22 S Range 12 W Sec. 22 County DOUGLAS

State OR Date 1-8-85 No. _____

Corner Designation

CE 1/16 S 22

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

Previous Renewals M 92-58, CS 58/290

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

FOUND BRASS CAP MONUMENT AT GRAVEL ROAD
INTERSECTION 8 INCHES BELOW SURFACE.

T 22 S R 12 W

C E 1/16 C
S 22
 1982
 LS 1091

Accessories Found:

CS 58/290

A 10" ALDER NOW A 12" DIA. 6' STUMP BARK SCRIBED "CE 1/16 S 22 BT"
BEARS N 6 1/2° W 24.1 FEET (REC. N 58° W 23.8 FEET).

5/8" DIAM. IRON ROD 15" ^{HIGH} ~~HEAT~~ BEARS SOUTH 42.7 FEET (REC. 42.2 FEET)

BT'S FROM M 92-58 EVIDENTLY DESTROYED DURING ROAD CONSTRUCTION
NOT FOUND.

#1754

