

GOVERNMENT CORNER RESTORATION FORM

Township 26 S Range 3 W Sec. 9 County DOUGLAS

State OREGON Date 1-25-85 No. _____

Corner Designation

AP NO. 18

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1972 BLM RESURVEY

Monument(s) Found: (Condition and Source)

1972 BLM BRASS CAP MONUMENT
WAS NOT FOUND. THE LOCATION OF
THE CORNER AND ONE OF THE
BT'S FALL IN A SLIDE AREA.

MONUMENT DETAIL

N/A

WE ESTABLISH A TEMP. POINT FROM
UNDISTURBED BT AS FOLLOWS

Accessories Found:

A 20" DIAM. FIR WITH WELL HEALED BLAZE AND BT TAG
BEARS N 11° W 63 ± FT. THIS TREE APPEARS TO BE UNDISTURBED

A 15" NOW 18" FIR WITH A WELL HEALED SINGLE BLAZE IS
DISLODGED BY SLIDE ACTIVITY BEARS N 23 1/2° E 49 ± FEET
REC. N 20° E 35 ± FT. TREE IS STILL STANDING BUT LEANING.

