

GOVERNMENT CORNER RESTORATION FORM

Township 28S Range 7W Sec. 19 County DOUGLAS

State OR Date 6/26/85 No. _____

Corner Designation

S19
S30

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1924 RESURVEY, REN #173

Monument(s) Found: (Condition and Source)

A US GENERAL LAND OFFICE SURVEY
DISK ON A I.P. PROTRUDING 5 IN.
ABOVE GROUND AND LEANING 5 IN.
WEST MARKED AS NOTED

US GENERAL LAND OFFICE SURVEY

MONUMENT RETURNED TO PLUMB,
FIRMLY SET AND PROTRUDING
8 IN. ABOVE GROUND.

T28S
S19
S30
R7W
1924

Accessories Found:

10" NOW A TIPPED OUT AND DOWN BADLY ROTTED OAK,
NO MARKS FOUND, A DEPRESSION IN GROUND BEARS N33°E,
29 FT AGREES WITH REC. (ORIG.).

12" NOW A 17" DIA. D. FIR WITH A DOUBLE FULLY HEALED BLAZE
BEARS S61°E, 11.2 FT AGREES WITH REC. (1924 RESURVEY).

27" NOW A 27" DIA. 4 FT HIGH D. FIR STUMP WITH A FULLY
HEALED LOWER BLAZE AND A PARTIALY HEALED UPPER BLAZE WITH
SCRIBING VISIBLE "WS 19 65" BEARS N35°E, 5.0 FT
AGREES WITH REC. (REN #173).

T28-7 #262

C.S. File No. 62/28-9

