

GOVERNMENT CORNER RESTORATION FORM

Township 255 Range 1E Sec. 25 County DOUGLAS

State OR Date 12/09/85 No. _____

Corner Designation

M.S. 501 COR. #4

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #28

Monument(s) Found: (Condition and Source)

A DC50 DISK ON AN I.P.
PROTRUDING 7 IN. ABOVE GROUND
MARKED AS NOTED. PER REN #28

DOUGLAS CO. SURVEYOR

T255

R1#E

M.S. 501

COR. 4

175

Accessories Found:

ORIG. BT'S

A 36" NOW 39" DIA. 3 1/2 FT HIGH D.FIR STUMP WITH A
PARTIAL WELL HEALED LOWER BLAZE, BEARS N60 1/4° W, 26.0 FT
AGREES WITH REN #28 (REC ORIG. N62° W, 26.0')

A 18" NOW 33" DIA. 7 FT HIGH D.FIR STUMP WITH A SINGLE
FULLY HEALED BLAZE, BEARS S14° W, 24.0' AGREES WITH REN #28
(REC. ORIG. S16° W, 24.0'). THIS BT WILL BE LOWERED
TO 2 FT BY MAY 1986 PER RON MURPHY N. UMCQA RANGER DIST.

#49

