

GOVERNMENT CORNER RESTORATION FORM

Township 22S Range 8W Sec. 27 County DOUGLAS

State OR Date 10/7/86 No. \_\_\_\_\_

Corner Designation

W.C.  
528 | 527

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals REN# 58 1962 BLM RESURVEY

Monument(s) Found: (Condition and Source)

A DC SO 2 1/2" DIA. BRASS CAP ON A 1 1/2" I.P.  
PROTRUDING 18 IN ABOVE GROUND.

MONUMENT DETAIL

COUNTY SURVEYOR'S OFFICE

T22S RBW

W.C.  
528 | 527

BLM

1962

1961

Accessories Found:

ORIG. BT'S

36" NOW 54" DIA. D.FIR WITH BARK SCRIBING VISIBLE "28 S" AND A  
H CHOPPED IN BARK FACING BE/I.P., BEARS S58 1/2° W 18.7 FT TO CENTER.  
(REC. ORIG. S59° W, BUM. S58 1/2° W, 17.2 FT, DIST. IS A FACE MEASUREMENT.)  
SOUTHEAST BT IS GONE A SLIGHT DEPRESSION FD. AT REC. BEARING  
AND DISTANCE.

REN#58 BT

8" FIR NOW 12" DIA 1 FT HIGH D.FIR STUMP BOTTOM OF BLAZE EVIDENT NO  
SCRIBING FOUND, BEARS N34 1/2° E, 12.2 FT (AGREES WITH REC.).

#169 X

