

RENEWAL

Monument Set (Procedure and Description)

NONE

Monument Detail

N/A

New Accessories

NONE

Sketch of Monument, Accessories, and General Area

N/A

Location & Comments

DALE BEATTIE (PROPERTY OWNER)
REQUESTED OCSO TO LOOK AT
OAK TREE THOUGHT TO BE
POSSIBLE BT TO NW COR DILL SI.
NO EVIDENCE OF BLAZES OR
SCRIBING FOUND. GROWTH RINGS
INDICATE TREE IS NOT THE RIGHT SIZE

Comp. Declin. _____

Agency OCSO

Party Chief RANDALL W SMITH

Notekeeper STEPHEN J. FLAUS

Witnesses DALE BEATTIE

Address

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Larry E. Monrean

OREGON
JULY 13, 1979
LARRY E. MONREAN
#1830