

GOVERNMENT CORNER RESTORATION FORM

Township 2RS Range 13W Sec. 13 County DOUGLAS

State OR Date 1/5/88 No. _____

Corner Designation

C 1/4

FILED
JAN 11 1988
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

MONUMENT DETAIL

Previous Renewals #9, #19

Monument(s) Found: (Condition and Source)

A 6" X 6" CONCRETE POST WITH
"U.S." MARKED ON EAST SIDE.
POST PROTRUDES 30" ABOVE GROUND, POSSIBLY
SET BY LIGHTHOUSE SERVICE, SEE DEPARTMENT OF
COMMERCE, LIGHTHOUSE SERVICE LETTER BETWEEN
R.R. TINKHAM (SUPERINTENDENT OF
LIGHTHOUSES) AND H.L. EPRSTEIN (COUNTY
SURVEYOR) IN C.S. FILE # 18/20A
DATED AUGUST 22, 1931

N/A

I.P. SET PER REN #9 NOT FOUND

Accessories Found:

BT'S PER REN #9

30" LEANING WEST SPRUCE NOW ROTTED STUMP NO BLAZES
OR SCRIBING FOUND N65°W, 45.0 FT (REC. N20°W, 47.0 FT).

36" NOW 52" DIA. 8 FT HIGH SPRUCE STUMP NO BLAZES OR
SCRIBING FOUND BEARS S5°E, 31.3 FT AGREES WELL WITH
REN #19, (ORIG. BEARING AND DISTANCE PER REN. #9 IS
S15°E, 30.0 FT.)

NE AND SW BT'S GONE

BT'S AND RO PER REN #19

16" NOW 21" DIA. D. FIR BEARS S25°W, 21.75 FT DISTANCE TO
NAIL ON EAST SIDE OF BT, 2 1/2" INSIDE BT, APPROX 3 FT ABOVE
GROUND (AGREES WELL WITH REC.).

6" NOW 10" HEMLOCK BEARS N39°W, 9.07 FT DISTANCE TO
NAIL ON EAST SIDE OF BT, 1" INSIDE BT, APPROX. 2 FT ABOVE
GROUND. (REC. N28 1/2°W, 9.07 FT)

A R.R. SPIKE IN AC. BEARS N85 1/2°E, 29.0 FT; 8 FT FROM
WEST EDGE OF A.C. (REC. S89 1/2°E, 29.0 FT)

STEEL POST WITH WHITE PALETTE MARKED "CY4S13" BEARS
S64°E, 2.1 FT

#27X

640 400

C.S. File No. 62/42-2

