

FILED

JK

NOV 28 1986

OREGON CORNER RESTORATION FORM

Section 16+17 Township 29S Range 8W

County DOUGLAS Date 9-26-86

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

Corner Designation

1/4 Sect. corner to Sec. 16+17

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out



Previous Renewals/Surveys, etc. Ren #90 OCT 1958
JAMES W BYRON

Monument(s) & Accessories Found: (Condition and Source)

Found A 2 1/2" BRASS CAP 1/4 corner common to Sect 17+16
READS 17/16, T29S, R8W. COUNTY SURVEYORS OFFICE DATED 1958
Set Flush with Ground. Also Found The Following Bearing
Trees

- A 18" cedar (Doubled) N 18° E 30° FT Posted BY Holt 8/20/71
- 30" Rotted OAK (original) N 85° E 79°
- 17" CEDAR NO TAG S 72° W 70° FT

Monument Detail



Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination _____
 Firm/Agency O. D. O. T.
 Address 1523 SE Cobb
Roseburg Ore
 Party Chief L. LATHROP
 Notes R. SMALL
 Witness R. WILCOX

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Roger E. Pattiz

OREGON
JULY 23, 1968
ROGER E. PATITZ
908