

CORNER RENEWAL
INTERNATIONAL PAPER COMPANY ENGINEER CREW

CORNER _____ SW _____ SEC. _____ 15 _____, T 23 S, R 8 W, Will. Mer.

	RECORD	FOUND	SET
MONUMENT	1967 Douglas County brass cap on I.P.	B.C./I.P. of record in good condition 6" out of ground.	Nothing
ACCESSORIES	28" D-Fir OBT (1967, 34" snag) N35E, 4.6 ft.	No evidence found	-
	40" Fir OBT (1967, 44" snag) S66E, 12½ ft.	44" D-Fir snag 60" high BLM tag reads "N66W, 12.5 ft."	IPCo. tag reads "N66W 11.5 ft."
	8" Fir OBT (1967 24") N77W, 23.1 ft.	18" D-Fir stump, face evident, N72W, 22.1 ft. Douglas Co. tag.	IPCo. tag reads "S72E, 22.1 ft." Covered stump top with galvanized metal.
	10" D-Fir S70W, 16.7. ft., scribed, 1967.	10" windthrown D-Fir BLM & Douglas Co. tags, S70W, 16.7 ft.	Nothing
	6" D-Fir S20W, 19.3 ft., scribed, 1967.	6" D-Fir broken off stump with Douglas Co. tag, S20W, 19.6 ft.	IPCo. tag on 1" x 4" stub reads "N20E, 19.6 ft."
	5" white fir N49E, 22.8 ft. scribed, 1967.	5" white fir stump BLM tag, N49E, 22.8 ft.	Nothing

Date: 5-2-86

INTERNATIONAL PAPER CO.
P. O. Box 43
Gardiner, Or 97441
Phone: 503-271-3688

FILED
JUN 2 1986
CLERK
DEPT. OF LAND SURVEY
CLATSOP COUNTY, OREGON

REGISTERED
PROFESSIONAL
LAND SURVEYOR

W. Carey Weatherly
OREGON
JULY 14, 1978
W. CAREY WEATHERLY
1967

C.S. File No. 63/37-1