

CORNER RENEWAL  
INTERNATIONAL PAPER COMPANY ENGINEER CREW

CORNER NE1/16 SEC. 2, T 23 S, R 9 W, Will. Mer.

RECORD	FOUND	SET
1982 BLM cadastral brass cap on 2½ I.P.	B.C./I.P. of record in good condition 6" above ground.	Nothing
10" Fir, N02E, 38½, LKS	Now 10" x 70" D-Fir stump, N02E, 38½ LKS, BLM tag, face galvanized metal, visible.	Covered stump top with galvanized metal.
25" Fir, S64½W, 17 LKS	Now 16" x 70" D-Fir stump S64½W, 17 LKS, scribing visible, BLM tag.	Nothing
No record	-	Nail in 20" D-Fir stump N15½W 39.5 ft., IPCo. tag.

**FILED**

*[Signature]*

JUN 12 1986

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

MONUMENT

ACCESSORIES

Date: 5-2-86

INTERNATIONAL PAPER CO.  
P. O. Box 43  
Gardiner, Or 97441  
Phone: 503-271-3688

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*W. Carey Weatherly*

OREGON  
July 14, 1978  
W CAREY WEATHERLY  
1667

C.S. File No. 63/37-2