

CORNER RENEWAL

INTERNATIONAL PAPER COMPANY ENGINEER CREW

CORNER C N 1/16 SEC. 33, T 20 S, R 10 W, Will. Mer.

MONUMENT	RECORD	FOUND	SET
ACCESSORIES	2 1/2" B.C. on 36" X 1 1/4" I.P. PLS 497. 1982	B.C./I.P. of record in good condition	Nothing
	32" Scribed Fir, S81 3/4 E, 90.3 ft.	32" D-Fir stump, face evident, S81 3/4E, 90.3 ft.	IPC0 tag reads "N81 3/4 W, 90.3 ft."
	28" Scribed Hemlock N 19 1/4 E, 36.5 ft.	28" Hem stump, face evident, N 19 1/4 E, 36.5 ft.	IPC0 tag reads "S 19 1/4 W, 36.5 ft."
			20" twin alder with IPC0 tag & nail bears S 23 1/4 W, 44.9 ft.

Date: 5/6/86

INTERNATIONAL PAPER CO.

P.O. Box 43

Gardiner, Or 97441

Phone: 503-271-3688

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

W. Carey Weatherly

OREGON
July 14, 1978
W CAREY WEATHERLY
1667