

FILED JP

OREGON CORNER RESTORATION FORM

AUG 17 1993

Section 6 Township 20S Range BW

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County DOUGLAS Date 2-19-93

CORNER DESIGNATION

NORTH 1/4 CORNER SECTION 6

- Condition Report Only
- Not Found
- Renewed
- Unrecovered
- Surveyed In
- Referred Out

Previous Renewals/Surveys, etc. ORIGINAL G.L.O. SURVEY BY WILLIAM P. WILKAT 1893-1894
1953-1954 H.L.M. SURVEY BY THOMAS TIGHE


Monument(s) & Accessories Found: (Condition and Source)

FOUND 1954 G.L.O. BRASS CAN OUT OF GROUND - RESET FROM EXISTING BEARING TREE
32" FIR BEAR. S56W, 26 1/2 BEAR. FACE
1954 B.T. - BEAR. FACE

Monument Detail

1/4 --- 531
56
1954

Sketch



Monument Set (Procedures and Description)

RESET 1954 MONUMENT & RECORD BEARING & DISTANCE FROM REMAINING BEARING
TREE.

New Accessories

9" FIR BEAR. N64W, 13' BEAR. (SCRIBED) 1/4 S318T"
5" FIR BEAR. S56E, 20S BEAR. (SCRIBED) 1/4 S68T"
9" HEMLOCK BEAR. N12W, 26 1/2 BEAR. (SCRIBED) 1/4 S318T"

Location & Comments

CORNER LIES IN A STEEP Compass Declination 20°
EAST SLOPE APPROX. 40° Firm
EAST OF RIVERTON Ward NorthWest Inc.
P.O. Box 105
Florence, OR 97439
Party Chief WAYNE DONOVAN
Notes
Witness MIKE HESSLER

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Wayne R. Donovan

OREGON
JULY 21, 1992
WAYNE R. DONOVAN
2553

EXPIRES 12/31/93