

GOVERNMENT CORNER RESTORATION FORM

FILED

*Handwritten initials*

Township 25S Range 7W Sec. 9 County DOUGLAS

DEC 18 1989

State OR Date 12/01/89

No. \_\_\_\_\_ COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Corner Designation \_\_\_\_\_

SMC  
S | 9

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals NONE


MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

3/4" BLM BRASS CAP ON A 2 1/2 O.D. IRON PIPE PROTRUDES 2 IN. ABOVE GROUND. (FROM 1985 BLM SURVEY)

U.S. DEPT. OF THE INTERIOR

SMC



1985

BUR. OF LAND MANAGEMENT

Accessories Found:

1985 BLM SURVEY BT'S

11" NW 11" DIA. D.FIR WITH A PARTIALLY HEALED SINGLE BLAZE, SCRIBING VISIBLE "S9 SMC BT" BEARS S29 1/2° E, 17.8 FT. (AGREES WITH RECORD).

10" NW 10" DIA. CEDAR WITH A PARTIALLY HEALED SINGLE BLAZE) SCRIBING VISIBLE "S9 SMC BT" BEARS S57° W, 9.3 FT (REC. 557° W, 8.9 FT; DIST. IS A FACE MEASUREMENT)

