

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 235 Range 4W Sec. 22 County DOUGLAS

State OR Date 2/12/90 No. _____

FEB 13 1990

Corner Designation _____

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

$\frac{1}{4}$ $\frac{S22}{S27}$

- ____ Condition Report Only
- ____ Not Found
- Renewed
- ____ Unrecorded
- ____ Surveyed In
- ____ Referenced Out

Previous Renewals 1976 BLM D. RESURVEY

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A 3 3/8" DIA. BLM BRONZE CAP ON
A 2 1/2" O.D. IRON PIPE, PROTRUDING
3" ABOVE GROUND. (1976 BLM)

U.S. DEPT. OF THE INTERIOR

1" O.D. IRON PIPE PROTRUDES 4"
ABOVE GROUND (SOURCE UNKNOWN)
BEARS N 43 1/2° E, 28.7 FT FROM
BLM BRASS CAP/IRON PIPE
SEE CS 54/16 FOR V.R. TRACY
REPORT ON I.P. IN 1965. WE
OPENED A 66" FIR STUMP TO THE
NE OF I.P. HAD PREVIOUSLY BURN
OPENED APPROX 1 FT INTO STUMP, WE
OPENED TO 15" OF CENTER NO
SCRIBING FOUND.

$\frac{1}{4}$ $\frac{S22}{S27}$

T235 R4W
1976

BUR. OF LAND MANAGEMENT

Accessories Found:

4" NOW 8" DIA. D. FIR WITH A FULLY HEALED SINGLE BLAZE
BEARS N 80 1/2° W, 5.0 FT. (AGREES WITH REC) 1976 BLM

4" NOW 10" DIA. D. FIR WITH A FULLY HEALED SINGLE BLAZE
BEARS S 1 1/2° E, 4.6 FT (AGREES WITH REC) 1976 BLM

ce

#183 +

SEARCH FOR $\frac{1}{4}$ $\frac{22}{27}$ T235 R4W

Fd. $\frac{3}{4}$ " I. PIPE FOR COR. - 66"

FIR STAMP N. 25° E. 297 FT

No scribe fd - matches bearing &

Dist. for orig. BT. No trace orig

S.W. BT. -

20" D. FIR S. 77° E. 14 1/2 FT

Find 2x face - NOT scribed - Numerous
CRUISERS MARKS.

I.P. lies 80 ft N. of FIRE TRAIL
COURSE E. & W.

NOV. 8, 1965

J.R.T.
M.S.
J.L.

FILED
RECEIVED

NOV 8 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. ~~54/16~~

NOV 16 1965

FILED
RECEIVED

[Handwritten signature]

J.R.T.
M.S.
J.L.

NOV 16, 1965

we find no orig scribed BTs
Reproduction in old Bank
This cor lies in Heavy
BARK scribed "1/4 S BT"

7" Laurel S. 20° E. 26 0 FT
One BT - NOT orig.

Fd. Haines 7" Iron for cor.

SEARCH FOR $\frac{1}{4}$ $\frac{23}{26}$ T235 R4W

6 2308
4 16149

CS 64/5