

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 30S Range 2W Sec. 20 County DOUG

78

APR 1 1991

State OREGON Date MARCH 19, 1991 No. _____

Corner Designation

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

20 | 21
29 | 28

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #172

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A 2 1/2 INCH DIAM. BRASS CAP (STAMPED AS AT RIGHT) ON A 1 1/2 INCH O.D. IRON PIPE FIRMLY SET AND PROTRUDING 1 FOOT ABOVE GROUND. NO EVIDENCE OF ORIGINAL CORNER MONUMENT FOUND.

COUNTY SURVEYORS OFFICE

T30 S R 2W

S20 | S21

S29 | S28

1968

Accessories Found:

EVIDENCE OF TWO ORIGINAL B.T.s A FIR, 24 IN. DIAM. NOW A 28 INCH DIAM. DOWN OUT OF POSITION, BROKEN AND BURNED SNAG WITH A POSSIBLE BURNED HEALED BLAZE, THE ROOT HOLE OF WHICH BEARS S04°E, 20 1/2 FEET DISTANT (AS PER RECORD).

A FIR 10 IN. DIAM NOW A 24 INCH DIAM, 4 1/2 FOOT TALL BURNED FIR STUMP WITH A FULLY HEALED DOUBLE BLAZE BEARS N76°W 230 FEET DISTANT (AS PER RECORD).

NO EVIDENCE OF THE NORTHEAST AND SOUTHWEST ORIGINAL BEARING TREES FOUND.

FROM RENEWAL #172 EVIDENCE OF ONE BEARING TREE FOUND. 6" D. FIR NOW AN 8 INCH DIAMETER DOWN OUT OF POSITION BURNED SNAG WITH A FULLY HEALED DOUBLE BLAZE, THE ROOT HOLE OF WHICH BEARS S58°W, 35 1/2 FT DISTANT.

#277 ✓

