

GOVERNMENT CORNER RESTORATION FORM

FILED JP

Township 21S Range 6W Sec. 22 County DOUGLAS

State OREGON Date APRIL 15, 1992 No. _____ MAY 1 1992

Corner Designation

1/4 22/27

COUNTY SURVEYOR
DOUGLAS COUNTY, OREGON
 Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

MONUMENT DETAIL

Previous Renewals #55 AND, 1979 BLM RESURVEY

Monument(s) Found: (Condition and Source)

FROM RENEWAL #55 A HAINES "T" IRON WITH
A BRASS WASHER MARKED "R.L.S. 239" PROTRUDES
10 INCHES FROM GROUND AND IS FIRMLY SET.
(THIS MONUMENT IS SET ON EDGE OF FOLLOWING MON.)
FROM 1979 BLM RESURVEY A BLM 3 1/4 INCH
DIAMETER BRASS CAP (MARKED AS AT RIGHT) ON
2 1/2 INCH DIAMETER IRON POST PROTRUDES 2
INCHES ABOVE GROUND AND IS FIRMLY SET.

U.S. BUREAU OF LAND MANAGEMENT

T215 R6W

1/4 S22
S27

1979

DEPT. OF THE INTERIOR

Accessories Found:

TWO ORIGINAL BEARING TREES FOUND THESE ARE ALSO B.T.'S FROM RENEWAL #55.
A FIR 16 INCH DIAM. NOW A 36 INCH D.B.H., D. FIR WITH A FULLY HEALED DOUBLE
BLAZE, DESCRIBED WITH THE BARK SCRIBING 1/4 S27 BT FROM RENEWAL #55,
BEARS S 50 1/2° E, 16 ± FEET DISTANT (ORIGINAL RECORD S 50 1/2° E, 15 ± FT. DIST, REAS-
ONABLE FOR A FACE MEASUREMENT).

A FIR 10 INCH DIAM. NOW A 3 1/2 FOOT TALL 16 INCH DIAMETER D. FIR STUMP
WITH A FULLY HEALED DOUBLE BLAZE, WITH THE BARK SCRIBING 1/4 S22 BT FROM
RENEWAL #55, BEARS N 50 1/2° W, 12 ± FEET DISTANT (AS PER 1979 RECORD, ORIGINAL
RECORD N 45° W, 12 ± FT. DIST.)

RENEWAL BEARING TREE FROM 1979 BLM RESURVEY. A FIR 10 INCH DIAM.
NOW A 17 INCH D.B.H., D. FIR WITH A FULLY HEALED DOUBLE BLAZE BEARS
N 04° W, 92 ± (B AND D. NOT CHECKED DUE TO REPROD. GROWTH BLOCKING MEAS-
UREMENT.)

