

GOVERNMENT CORNER RESTORATION FORM

Township RBS Range 7 1/2 Sec. 7 County DOUGLAS

Date: 6/22/94 By: JP

State OR Date 5-23-94 No. _____

This survey consists of:
Map _____
Narrative _____
Corner Rpt: C.S. 64/51

Corner Designation

1/4
S 7
ONLY

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals

Monument(s) Found: (Condition and Source)

A 2 1/2" BRASS CAP ON A 1" O.D.
IRON PIPE PROTRUDING 8"
ABOVE GROUND. (1924)

U.S. GENERAL LAND OFFICE

1/4
S 7
R 7 1/2

1924

SURVEY

Accessories Found:

16" NOW 22" DIA. D.FIR WITH A FULLY HEALED SINGLE
BLAZE BEARS N 5° W, 17.6 FT (REC' N 5° W 18.5 FT)
OBT

12" NOW 17" DIA D.FIR WITH A FULLY HEALED SINGLE
BLAZE BEARS S 41° W, 12.5 FT (AGREE WITH REC)
OBT

