

GOVERNMENT CORNER RESTORATION FORM

Date: 8/17/94 By: PC

Township 26S Range 5W Sec. 35 County DOUGLAS

This survey consists of

State OR Date 6-22-94 No.

Map:

Narrative:

Corner Rpt: CS 64/52

Corner Designation

1/4 S 35 S 2

DOUGLAS COUNTY

- Condition ~~Surveyed~~
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals 1964 GODFREY PI# 540100

Monument(s) Found: (Condition and Source)

A 2 1/2" BRASS CAP ON A 1 1/2" O.D. IRON PIPE PROTRUDING 16" ABOVE GROUND (1964)

COUNTY SURVEYORS OFFICE

T 26S

1/4 S 35 R S 2 5 W

T 27S

1964

Accessories Found:

ORIG SW BT NOW GONE

24" NOW 48" DIA. B. OAK WITH A POSSIBLE SCAR BEARS N 61° W, 87.1 FT (REC N 48° W, 87.1 FT) OBT

9" NOW 14" DIA. W. OAK WITH A FULLY HEALED DOUBLE BLAZE, BEARS S 20° W, 58.0 FT (AGREES WITH REC) 1964

12" NOW 13" DIA W. OAK WITH A FULLY HEALED DOUBLE BLAZE, BEARS N 79° W, 85.6 FT (AGREES WITH REC) 1964

