

GOVERNMENT CORNER RESTORATION FORM

Date: 5-31-95 By: AP

Township 30S Range 2W Sec. 14

County DOUGLAS This survey consists of:

State OR Date 10-27-94

No. _____ Narrative: _____
Corner Rpt: C.S. 64/58-5

Corner Designation

1/4 S 15 | S 14

DOUGLAS COUNTY

- Condition Survey Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1963 BLM

Monument(s) Found: (Condition and Source)

3/4" BRASS CAP ON A 2 1/2" O.D.
IRON PIPE, LOOSELY SET, PROTRUDES
21" ABOVE GROUND. BC/IP LEANS
18" SOUTH OF PLUMB. (1963 BLM)

UNMARKED 10" X 10" X 6" CONGLOMERATE
STONE FOUND LOOSE ALONG SOUTH
WEST EDGE OF BC/IP (CORIG?)

U.S. CADASTRAL SURVEY
1/4

S15 | S14

T30S R2W
1963

BUREAU OF LAND MANAGEMENT

NOTE:
EVIDENCE OF GROUND BEING
DISTURBED IN AREA AROUND CORNER
POSITION OF FO BC/IP DOES NOT FIT
WELL WITH REMAINING BT'S. WE
CALCULATE A POSITION FOR CORNER
BASED ON REMAINING BT'S. TOP
OF BRASS CAP SHOWS EVIDENCE OF
BEING HIT.

Accessories Found:

(BRG + DIST. TAKEN FROM POSITION DETERMINED FROM BT'S)
18" NOW ROTTEN 5' HIGH MARBONE STAB. NO MARKS
VISIBLE, BEARS S 49° W, 21.1 FT (AGREES WITH 1963 BLM) OBT

ORIG SOUTH EAST PINE NOW GONE

13" NOW 19" DIA D.F. FIR WITH A FULLY HEALED DOUBLE
BLAZE, BEARS S 12° E, 23.8 FT (AGREES WITH REC)
1963 BLM

19" NOW 23" DIA. DOWN D.F. FIR WITH A FULLY HEALED
SINGLE BLAZE, ROOT HOLE IS LARGE AND INDEFINITE,
(REC. S 72° W, 38.3 FT) 1963 BLM

Monument Set (Procedure and Description)

POSITION OF 1963 BLM BC/IP IS REFERENCED WITH A 5/8" BY 32" LONG IRON ROD WITH A DCSO ALUM CAP MARKED "B01 1995". I.R. PROTRUDES 4" ABOVE GROUND.

1963 BLM BRASS CAP IRON PIPE MEASURES 28" LONG IS SET AT A POINT DETERMINED FROM REMAINING BEARING TREES. THE MARKS "RESET 1995 DCSO" ARE ADDED. BC/IP NOW PROTRUDES 8" ABOVE GROUND.

U.S. CADASTRAL SURVEY

1/4

S15/S14
DCSO
T30S R2W
RESET 1995

1963

BUREAU OF LAND MANAGEMENT

New Accessories

9" DIA D.FIR DOUBLE BLAZED AND SCRIBED "1/4 S14 CS BT" BEARS S74 1/2° E, 19.4 FT. TO CENTER OF ROOT CROWN.

4" DIA. D.FIR DOUBLE BLAZED AND SCRIBED "X BT" BEARS S60° W, 9.4 FT

5/8" I.R. WITH A DCSO ALUM. CAP MARKED "B01 1995" BEARS S84 1/2° E, 6.4 FT

Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER LIES ON A STEEP SOUTH SLOPE IN A NORTH - SOUTH FENCE LINE

Comp. Declin. 17 3/4° E
Agency DCSO
Party Chief RANDALL W. SMITH
Notekeeper [Signature]
Witnesses STEPHEN J. ELANK

Address

REGISTERED Surveyor's Seal
PROFESSIONAL
LAND SURVEYOR

Randall W Smith

OREGON
JULY 25, 1990
RANDALL W. SMITH
2469

EXPIRES 6/30/96

