

GOVERNMENT CORNER RESTORATION FORM

Date: 4/26/96 By: AC

Township 27S Range 6W Sec. _____ County DOUGLAS

This survey consists:

State OR Date 4-3-96 No. _____

Map: _____

Narrative: _____

Corner Designation

SE
COR
DLC 64

AS DETERMINED
IN 1958 BY
G.R. LECKLIDER

Corner Rpt: 64/66-12

Condition DOUGLAS COUNTY

Not Found SURVEYOR

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals 1958 LECKLIDER PI#060404

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

5/8" IRON ROD PROTRUDING 5"
ABOVE 3 STONES (1958)

N/A

Accessories Found:

30" BLACK OAK NOW 48" DIA 12' HIGH RATTENING
OAK SNAG SHOWING AN UNHEALED PREVIOUSLY OPENED BLAZE,
NO SCRIBING FOUND, BEARS S 86° E, 388.4 FT
(ORIG REC S 86° E, 434.9 FT, 1958 REC
S 84° E, 380.3 FT) CRT?

24" NOW 33" DIA DOWN D. FIR WITH A FULLY
HEALED BLAZE, ROOT HOLE BEARS S 79° W, 17.5 FT
(REC S 79° W 27.5 FT BT TAG CONFIRMS 17.5 FT)
1958

22" NOW 36" DIA 2 FT HIGH D. FIR STUMP WITH A
FULLY HEALED BLAZE, BEARS SOUTH 16.0 FT
(AG REES WITH REC.) 1958

