

GOVERNMENT CORNER RESTORATION FORM

Date: MAR. 31, 1997 By: PC

Township 28S Range 6W Sec. 7

County DOUGLAS This survey consists of:

State OR Date 3-11-97 No. _____

Map _____
Name _____
Commission 64/71-19

Corner Designation

S12 | S7

S13 | S18

- DOUGLAS COUNTY
Condition: Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals 1958 DCSO

Monument(s) Found: (Condition and Source)

2 1/2" DIA BRASS CAP ON A 1 1/2" O.D. IRON PIPE PROTRUSING 1 1/2" ABOVE GROUND (1958 DCSO)

COUNTY SURVEYORS OFFICE

R	S12 S7	R
7	---	6
W	S13 S18	W
	T28S	
	1958	

Accessories Found:

NO ART'S FOUND

14" NOW REMAINS OF OAK ROOTS, N 4 1/2° W, 50.0 FT
CRK N 3 9/2° W, 50.0 FT) 1958

14" NOW 35" DIA W/OAK WITH A FULLY HEALED DOUBLE
BLAZE, BEARS N 13 1/4° E, 88.0 FT (CRK N 14 1/2° E, 88.0 FT)
1958

14" NOW 23" DIA W/OAK WITH A FULLY HEALED DOUBLE
BLAZE, BEARS S 55 1/2° W, 133.7 FT (AGREES WITH REC)
1958

