

Date: 3/31/1997 By: BC

GOVERNMENT CORNER RESTORATION FORM

This survey consists of:

Township 29 S Range 5 W Sec. 28 County DOUGLAS

Map: _____

State OR Date MARCH 14, 1997

No. _____

Narrative: _____
Corner Rpt: CS 64/71-22

Corner Designation

SW COR DLC 45

045030

DOUGLAS COUNTY
SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals CS 43/17 M 99-65

Monument(s) Found: (Condition and Source)

ORIGINAL MONUMENT NOT FOUND

2" OUTSIDE DIAM. IRON PIPE
(1 1/2" INSIDE DIAM. PER CS 43/17)

SOURCE OF MONUMENT: ~~BT~~ FOUND
BY WENDSBOTH NOT KNOWN.

Accessories Found:

ORIGINAL BLACK OAK BT NOT FOUND

BT PER CS 43/17 18" W OAK NOW DEAD 18" DIAM. BEARS N 76° W 3' FT
TO FACE HAS WELL HEALED DOUBLE GRAZE

~~NOTE: SOURCE~~

✓045030

CS. PNO 194. 64/71-22

