

GOVERNMENT CORNER RESTORATION FORM

Date: 5/8/97 By: PC

This survey consists of:

Township 26 Range 6W Sec. 30 County DOUGLAS
 State OR Date 4-9-97 No. _____
 Narrative: _____
 Corner Rpt: CS 64/74-16

Corner Designation

S25 | S30

 S36 | S31

DOUGLAS COUNTY SURVEYOR

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

Previous Renewals 1967 GARRETT

Monument(s) Found: (Condition and Source)

2 1/2" DIA. BRASS CAP ON 1 1/2" O.D. IRON PIPE, PROTRUDES 12" ABOVE GROUND (1967)
1/2" I.D. IRON PIPE PROTRUDES 7" ABOVE GROUND. IS A LONG WEST EDGE OF B/LP (SOURCE UNKNOWN, POSSIBLE EPSTEIN SURVEY IN 1939 M16-1)

MONUMENT DETAIL

T265
 R S25 | S30 R
 7 S36 | S31 6
 W L.S. 54f W
 1967

Accessories Found:

NO EVIDENCE OF ORIG. BT'S FOUND. LAND OWNER MORLEY HOUSTON REMEMBERS AN OAK STUMP WITH MARKS IN GENERAL AREA OF ORIG. SE BT LOCATION

6" NOW 11" DIA. B. OAK WITH A FULLY HEALED DOUBLE BLAZE, BEARS N50°W, 63 FT (AGREES WITH REC.) 1967

9" NOW 12" DIA B. OAK WITH A FULLY HEALED DOUBLE BLAZE, BEARS S64°E, 30.7 FT (AGREES WITH REC) 1967

7" OAK NOW 14" DIA ASH WITH A FULLY HEALED DOUBLE BLAZE, BEARS N2°E, 65.8 FT (AGREES WITH REC) 1967

