

GOVERNMENT CORNER RESTORATION FORM

Date: 5-23-1997 By: BC

Township 22S Range 9 Sec. 7
State OK Date 5-17-97

County DOUGLAS This survey consists of:
Narrative
Corner CS 64/74-33

Corner Designation

DLC
50

DOUGLAS COUNTY
Condition Renewed
Not Found
 Renewed
Unrecorded
Surveyed In
Referenced Out

PI# 050020

Previous Renewals 1916, 1920, 1936, 1962 AND 1978 DCSO

MONUMENT DETAIL

Monument(s) Found: (Condition and Source),
2 1/2" DIA BRASS CAP ON A 1 1/2"
O.D. IRON PIPE, PROTRUDS 3"
ABOVE GROUND (1978)

DOUGLAS COUNTY SURVEYOR
T22S R8W
50 FT. DUE WEST
TO

DUG 3 FT INTO SAND
CHECKED WITH METAL
DETECTOR WAS UNABLE
TO LOCATE GUN BARREL
OR CONCRETE BLOCK.

NWCOR
DLC50

WITNESS COR
1978

Accessories Found:

FROM CORNER POSITION BT'S ARE FOUND AS NOTED
IN 1978 RENEWAL AND A CLUMP OF BROKEN
MYRTLE'S, LARGEST BEING 14" DIA NO BLAZES
VISIBLE CLUMP FITS POSITION OF NW MYRTLE BT'S
MARKED IN 1916 AND 1962.

FROM WIT. CORNER POSITION (BC/IP)

8" NOW 19" ASH MARKED IN 1920 WITH A FULLY HEADED
BLAZE AND PREVIOUSLY OPENED ROTTEN WITH BLAZE
FACING TRUE CORNER POSITION. BEARS N76°W, 43.2 FT
(AGREES WITH RCL). 1920

15" NOW 20" DIA. MYRTLE MARKED FOR TRUE CORNER
POSITION IN 1962 NO BLAZE VISIBLE, BEARS
S57°W, 52.9 FT TO CENTER OF ROOT CROWN
(AGREES WITH RCL) 1962

10" NOW 18" DIA MAPLE WITH A FULLY HEADED
DOUBLE BLAZE, BEARS S8°E, 11.4 FT (AGREES
WITH RCL.) 1978

