

GOVERNMENT CORNER RESTORATION FORM

Date: 7/17/97 By: BC

Township 255 Range SW Sec. 25 County DOUGLAS

This survey consists of:

State OK Date 7-10-97 No. _____

Map: _____

Corner Designation AS DETERMINED

Narrative: _____

Corner Rpt: CS 64/75-26

$\frac{1}{4} \frac{525}{536}$

BY M 33-71

- DOUGLAS COUNTY
 Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals 1970 BENTZ M33-71

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

5/8" IRON ROD PROTRUDES 8"
ABOVE GROUND (1970)

N/A

Accessories Found:

NO OBJ'S FOUND

13" NOW 24" DIA 3 FT HIGH D.F.R. STUMP
WITH A FULLY HEALED SINGLE BLAZE BEARS
S29°E, 70.3 FT (REC. S29°E 167.5 FT?) 1970

7" NOW 21" DIA D.F.R. WITH A FULLY HEALED
SINGLE BLAZE BEARS N13°W, 32.2 FT
(AGREES WITH REC.) 1970

