

Date: 11-15-96 By: JP

GOVERNMENT CORNER RESTORATION FORM

This survey consists of:

Township 25S Range 2W Sec. 15

County DOUGLAS

Map: \_\_\_\_\_

State OR

Date 9-26-96

No. \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: C.S. 65/9-19

Corner Designation \_\_\_\_\_

DOUGLAS COUNTY SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

$\frac{1}{4}$   $\frac{S15}{S22}$

Previous Renewals #33, 1962 BLM

Monument(s) Found: (Condition and Source)

3/4" DIA. BRASS CAP ON A 2 1/2" O.D. IRON PIPE, PROTRUDES 3" ABOVE GROUND. (1962 BLM)

1/2" I.D. IRON PIPE PROTRUDES 1/3" ABOVE GROUND, ALONG NE 1/4 EDGE OF BC/IP. (#33)

FOUND A BROKEN STONE THAT MEASURES 24" X 10" X 6" NO MARKS FOUND. STONE IS ALONG NORTH EDGE OF BC/IP (ORIG COR. STONE)

U.S. DEPT. OF THE INTERIOR

$\frac{1}{4}$   $\frac{S15}{S22}$   
T25S R2W  
1962

BUR. OF LAND MANAGEMENT

Accessories Found:

30" NOW 29" DIA. 15 FT HIGH HEMLOCK SNAG WITH SCRIBING VISIBLE ON AN UNHEALED BLAZE "1/4 S22 53 BT" BEARS S 54 1/2° W, 21.8 FT (AGREES WITH REC) REN #33

12" NOW 23" DIA. 3 FT HIGH <sup>Hemlock</sup> STUMP, SCRIBING FD. "1/4 S1" AND A HEALED BLAZE, BEARS N 39° W, 5.3 FT (AGREES WITH REC.) OBT

8" NOW 10" DIA. 25 FT HIGH CEDAR SNAG WITH A ROTTED BLAZE, NO SCRIBING VISIBLE, BEARS S 15° E, 21.1 FT (AGREE WITH REC.) OBT

